30423R001600610001-6 25X1X6 COMPTOSMOTAT 25X1A2g CENTRAL INTELLIGENCE AGENCY INFORMATION REPORT COUNTRY Greece REF Utilization of US-Furnished Tactical Aircraft-T-33s SUBJECT RESPONSIVE TO CD NO! PLACE ACQUIRED 00/C NO. This uncrewated information for US Officials (BY SOURCE) 25X1A6a ORR NO. Only is supplied to the no sible interest of DAS NO. your analysis. It does not warrent dissemi-DATE ACQUIRED (BY SOURCE) OCI NO. nation by 00-P Contact DATE DISTR. DATE (OF INFO.) Jun 54 25X1A9a NO. OF PAGES LEANING OF TITLE 18. SECTIONS 76 25X1X6 ND 794, OF THE U.S. CODE. AS AMENDED TRANSMISSION OR REVE NO. OF ENCLS ATION OF ITS CONTENTS TO OR RECEIPT BY AN UNAU 25X1A2g SUPP, TO THIS IS UNEVALUATED INFORMATION REPORT NO. SOURCE Operational Data: During the month of June 1954, US T-33 aircraft at the Royal Hellenic Air Force RHAF Base, Elevsis, Greece, were utilized in transition, instrument, night flying and battle tactical flying. There were no special missions flown during the month. a. Flight time for the month was governed by a number of personnel factors: The second group of cadets from the Tatoi Air College started flying T-33s on 7 Jun 54. There are 36 students in this group of cadets. Another problem was that class 16, made up of 10 commissioned officers, finished jet training on 22 Jun 54 after starting training on 26 May 54. Another problem was that 13 pilots of the 335th Squadron and 348th Flight took the instrument training course during June (seven received their instrument cards). Six of these pilots will continue with the instrument course. In addition, three pilots who failed to pass primary jet training were given 10 additional hours of training. b. Because of the problems noted above, total flight time for the month was 870 hours with an in-commission rate of 91 per cent, five per cent out for maintenance, and four per cent out of commission for parts. There were no weather or refueling problems in June 1954. 2. Maintenance and Repair Data: Maintenance personnel problems have stabilized in the last three months and there is a fairly consistent rate of personnel turnover. This has resulted in a better routing of aircraft to the flight line. Major inspections are now accomplished in a day and a half. The supply problem continues, with the fault lying mainly with the RHAF supply personnel. The main stumbling block is getting the initial requisition submitted. Once this is done, there is an inadequate follow-up procedure for these requisitions. Utheration of US account 13-53.5 U.S. Officials Only 15-54.1

This Approved to Release the Server the Intelligence 3-00423 to 16006 10001 for Agencies indicated above. It is not to be transmitted overseas without the concern of the originating office through the Assistant Director of the Office of Collection and Dissemination, CIA.